

# CASE STUDY

## Woodwork

### BURNT OUT EXTRACTOR REPLACED WITH NEW LARGER CAPACITY UNIT

#### ISSUE

Exeon were asked in to provide a quote for a carpentry workshop which had a Dust Extractor destroyed by fire. The Extractor was completely unusable and the ductwork only partly so.

Operations were unsuccessfully attempting to continue production without the extraction which was desperately required.

#### SOLUTION

Within just 3 weeks, Exeon were back on site installing a larger new dust extractor with future capacity and ensuring the production team could continue at maximum efficiency; this turnaround included working in with the complications of insurance.

#### PROJECT VALUE

# £18,000

Ref: C145279

