

CASE STUDY

REPLACEMENT DUST EXTRACTION SYSTEM - D&T ROOM AT COLLEGE

ISSUE

Exeon were asked to provide a replacement Dust Extractor for a D&T Room at a school. The Existing Extractor had failed.

The Airflow capabilities of the existing system were unknown.

The Existing extract unit required to be craned out of a very awkward location.

SOLUTION

Exeon carried out an investigation to assess the level of airflow needed, with extensive discussions over diversity of use and investigations over levels of airflow.

Exeon supplied and installed a Rhino 40 successfully, and were able to overcome the logistics challenges and remove the existing unit off site.

PROJECT VALUE

£30,000

Ref: 146509

